Technical Information OCCS50

Sensor for determining chlorine dioxide



OCCS50 offers high-precision measurement with long-term stability to guarantee optimum process monitoring

Application

- Drinking water to guarantee reliable disinfection
- Cooling water to prevent the growth of biofilms and pathogens
- Food to guarantee food safety
- Auxiliary equipment or utility services to ensure the absence/presence of chlorine dioxide

Your benefits

- Fast response time (t₉₀ < 15 s) provides an accurate process view and enables prompt reaction to process changes as well as efficient process control.
- Increased process safety: precise and long-term stable measurement ensures consistent process monitoring and allows for individually adapted disinfectant dosing
- Flexible installation: sensor can be installed in the OCCA151 and OCA250 flow assemblies or in immersion assemblies. Measurement virtually flow independent at flow velocities above 5 l/h (OCCA151), 30 l/h (OCA250) or above 15 cm/s (immersion).
- The low-maintenance, amperometric sensor reduces the cost of ownership of the measuring point, particularly compared to colorimetric measuring systems.
- Connection to the Liquisys chlorine transmitter ensures continuity for the installed base of analog chlorine dioxide measuring points.

Function	and	system	design

Measuring principle	Chlorine dioxide levels are determined in accordance with the amperometric measuring principle.					
	The chlorine dioxide (ClO_2) in the medium diffuses through the sensor membrane and is reduced to chloride ions (Cl^-) at the gold cathode. At the silver anode, silver is oxidized to silver chloride. Electron donation at the gold cathode and electron acceptance at the silver anode cause a current to flow which is proportional to the concentration of chlorine dioxide in the medium. This process does not depend on the pH value over a wide range.					
	The transmitter uses the current signal to calculate the measured variable for concentration in mg/l (ppm).					
Function	 The sensor consists of: Membrane cap (measuring chamber with membrane) Sensor shaft with anode with large surface area (counter-electrode) and a cathode embedded in plastic (working electrode) 					
	The electrodes are in an electrolyte which is separated from the medium by a membrane. The membrane prevents the electrolyte from leaking and protects against contaminant penetration.					
	The measuring system is calibrated by means of a colorimetric comparison measurement in accordance with the DPD method for chlorine dioxide. The calibration value determined is entered in the transmitter.					
Cross-sensitivities 1)	Free chlorine, ozone, free bromine					
	There were no cross-sensitivities for: H_2O_2 , peracetic acid					
Measuring system	A complete measuring system comprises: Disinfection sensor OCCS50 (membrane-covered, Ø25 mm) with corresponding installation adapter Flowfit OCCA151 flow assembly Transmitter, e. g. Liquisys OCM223/253 Optional: Flowfit OCA250 flow assembly (if a pH/ORP sensor is to be installed in addition) Optional: Immersion assembly Flexdip CYA112 Optional: proximity switch					

¹⁾ The listed substances were examined with different concentrations. An additive effect has not been investigated.



• 1 Example of a measuring system

- Liquisys OCM223/253 transmitter 1
- Power cable for transmitter 2
- Disinfection sensor OCS50 (membrane-covered, Ø25 mm) 3
- Outlet from Flowfit OCCA151 flow assembly 4
- Inlet to Flowfit OCCA151 flow assembly Flowfit OCCA151 flow assembly 5
- 6
- Union nut for installing a disinfection sensor in the Flowfit OCCA151 flow assembly 7
- 8 Fixed cable of OCCS50 disinfection sensor
- Ground the medium at the sensor by means of the PML pin to ensure a high reading stability.

Input

Measured variables	Chlorine dioxide (ClO ₂)	[mg/l, µg/l, ppm, ppb]
	Temperature	[°C, °F]
Measuring ranges	OCCS50**11AD OCCS50**11BF	0 to 5 mg/l (ppm) ClO_2 0 to 20 mg/l (ppm) ClO_2
Signal current	OCCS50**11AD OCCS50**11BF	135 to 250 nA per 1 mg/l (ppm) ClO_2 35 to 65 nA per 1 mg/l (ppm) ClO_2

Power supply

Electrical connection

► Install the grounding bar (order number 51501086) in accordance with the accompanying instructions in order to guarantee a high reading stability.

NOTICE

Measured errors due to faulty connection

▶ When connecting the sensor cable, make sure that the black semi-conductor layer is removed as far as the inner shield.

The sensors have a fixed cable of 3 m (9.8 ft) maximum in length.

• Connect the sensors to the transmitter according to the following diagram:

Sensor: assignment	Sensor: core	Transmitter: terminal
Outer shield		S
Anode	[A] red	91
Cathode	[K] transparent	90
NTC temperature sensor	Green	11
NTC temperature sensor	Brown	12



- 2 Structure of the sensor cable
- 1 Outer shield
- 2 Inner shield, anode
- 3 Semi-conductor layer
- 4 Inner insulation
- 5 Inner conductor, measured signal
- 6 Temperature sensor connection
- 7 2nd insulation
- 8 Outer insulation

Reference operating	Temperature	20 °C (68 °F)		
conditions	pH value	pH 6 to 7		
	Flow	40 to 60 cm/s		
	ClO ₂ -free base med	ium Deionized water		
Response time	T ₉₀ < 15 s (after cor	npleting polarization)		
Measured value resolution of	OCCS50**11AD	0.03 µg	/l (ppb) ClO ₂	
sensor	OCCS50**11BF	0.13 µg	/l (ppb) ClO ₂	
Measured error ²⁾	n which value is higher)			
		LOD (limit of detection)	LOQ (limit of quantification)	
	OCCS50**11AD	0.0007 mg/l (ppm)	0.002 mg/l (ppm)	
	OCCS50**11BF	0.0013 mg/l (ppm)	0.004 mg/l (ppm)	
Repeatability	OCCS50**11AD	0.002 mg/l (ppm)		
	OCCS50**11BF	0.007 mg/l (ppm)		
Nominal slope	OCCS50**11AD	195 nA per 1 mg/	'l (ppm) ClO ₂	
	OCCS50**11BF	50 nA per 1 mg/l	(ppm) ClO ₂	
Long-term drift	< 1 % per month (mean value, determined while operating at varying concentrations and un reference conditions)			
Polarization time	Initial commissionin	ng 60 min		
	Recommissioning	30 min		
Operating time of the	at maximum conce	ntration and 55 °C	60 days	
electrolyte	at 50 % of measurin	ng range and 20 °C	1 year	
	at 10 % of measuring	2 years		

Performance characteristics

²⁾ Based on ISO 15839. The measured error includes all the uncertainties of the sensor and transmitter (measuring chain). It does not contain all the uncertainties caused by the reference material and adjustments that may have been performed.



the sensor must not exceed 1 bar (14.5 psi) and must remain constant.

To avoid buildup, heavily contaminated water should also be filtered.

Avoid negative pressure at the sensor, e.g. due to medium being returned to the suction side of a

Installation

pump.

►

Orientation

Do not install upside-down!

 Install the sensor in an assembly, support or appropriate process connection at an angle of at least 15 ° to the horizontal.

Preparing assembly

1. The assembly is supplied to the customer with a union nut screwed onto the assembly: unscrew union nut from assembly.



■ 3 Flowfit OCCA151 flow assembly

1 Union nut

2. The assembly is supplied to the customer with a dummy plug inserted in the assembly: remove dummy plug from assembly.

Equip sensor with adapter

The required adapter (clamping ring, thrust collar and O-ring) can be ordered as a mounted sensor accessory or as a separate accessory $\rightarrow \cong 12$.

1. First slide the clamping ring, then the thrust collar, and then the O-ring from the membrane cap towards the sensor head and into the lowergroove.



Ide Slide clamping ring, thrust collar and O-ring upwards from the membrane cap to the sensor shaft and into the lower groove

Installing sensor in assembly

2. Slide sensor with adapter for Flowfit OCCA151 into the opening in the assembly.

3. Screw union nut onto assembly onblock.



- 5 Flowfit OCCA151 flow assembly
- 1 Disinfection sensor
- 2 Flowfit OCCA151 flow assembly
- 3 Union nut for securing a disinfectionsensor

Installation in Flowfit OCA250 flow assembly

The sensor can be installed in the Flowfit OCA250 flow assembly. It allows a pH and ORP sensor to be installed, in addition to the chlorine or chlorine dioxide sensor. A needle valve regulates the flow in the range of 30 to 120 l/h (7.9 to 30 gal/h).

Please note the following during installation:

- ► The flow rate must be at least 30 l/h (7.92 gal/h). If the flow drops below this value or stops completely, this can be detected by an inductive proximity switch and used to trigger an alarm with locking of the dosage pumps.
- If the medium is returned to an overflow basin, pipe or similar, the resulting counterpressure on the sensor must not exceed 1 bar (14.5 psi) and must remain constant.
- Negative pressure at the sensor e.g. due to medium being returned to the suction side of a pump, must be avoided.

Equip sensor with adapter

The required adapter can be ordered as a mounted sensor accessory or as a separate accessory. $\rightarrow \cong$ 12

1. Slide adapter for Flowfit OCA250 from the sensor head up to the stop on the sensor.



Ide on adapter for Flowfit OCA250.

2. Lock the adapter in place using the two studsprovided.

For detailed information on "Installing sensor in Flowfit OCA250 assembly", see Operating Instructions for assembly

Installation in other flow assemblies

When using other flow assemblies, please ensure the following:

- ▶ The flow velocity at the membrane must always be at least 15 cm/s (0.49 ft/s).
- The flow direction is upwards. Transported air bubbles must be removed so that they do not collect in front of the membrane.
- The flow must be directed to the membrane.

Installation in Flexdip CYA112 immersion assembly

Alternatively, the sensor can be installed in an immersion assembly with G1 threaded connection, e. g.

Equip sensor with adapter

The required adapter can be ordered as a mounted sensor accessory or as a separate accessory. $\Rightarrow \cong 12$

1. Slide adapter for Flexdip CYA112 from the sensor head up to the stop on the sensor.



- In Slide on adapter for Flexdip CYA112.
- 2. Lock the adapter in place using the two studs provided.



For detailed information on "Installing sensor in Flexdip CYA112 assembly", see Operating Instructions for assembly

Environment

Ambient temperature range -20 to +60 °C (-4 to 140 °F)

Storage temperature		Longterm storage	Storage up to max 48 h	
	With electrolyte	+0 to 35 $^\circ \!\! C$ (32 to 95 $^\circ \!\! F$) (non-freezing)	35 to 50 °C (95 to 122 °F) (non-freezing)	
	Without electrolyte	−20 to 60 °C	(-4 to 140 °F)	

Degree of protection

IP 68 (1.8 m (5.91 ft)) water column over 7 days at 20 $^\circ C$ (68 $^\circ F)$

Process

Process temperature	+0 to 55 °C (32 to 130 °F), non-freezing					
Process pressure	The inlet pressure depends on the specific fitting and installation.					
	The measurement can take place with a free outlet.					

The medium	pressure	directly upstre	am from t	he sensor	membrane	must not	exceed 1	bar (1	14.5 psi)
abs.										

• In terms of sensor condition and performance, it is essential that the flow velocity limits specified in the following table be observed.

		Flow	Volume flow [l/h]					
		velocity [cm/s]	Flowfit OCA250	Flowfit OCCA151	FlexdipCYA112			
	Minimum	15	30	5	The sensor is suspended freely in the			
	Maximum	80	145	20	medium; pay attention to the minimum flow velocity of 15 cm/s during installation.			
pH range	Stability range of ClO	2	рH	2 to 10 ¹⁾				
	Calibration	Calibration pH 4 to 8						
	Measurement	Measurement pH 4 to 9						
	From pH values > 9, 0	ClO ₂ is unsta	ble and deco	omposes.				
	1) Up to pH 3.5 and	in the presend	ce of Cl ions, f	ree chlorine is p	roduced and included in the measurement			
Flow	remains stable for a n	ninimum of	5 l/h (1.32	gal/hr), in the	Flowfit OCCA151 flow			
	assembly remains sta	assembly remains stable for a minimum of 30 l/h (8 gal/hr), in the Flowfit OCA250 flow						
	assembly			-				
Minimum flow	remains stable for a n	ninimum of	15 cm/s (0.	5 ft/s), e.g. wit	h Flexdip CYA112 immersion assembly			

Mechanical construction





Weight	Sensor with membrane cap and adapter)	Sensor with membrane cap and electrolyte (without protection cap and without adapter)					
Materials	Sensor shaft	PVC					
	Cable sheathing	Cable sheathing PVC					
	Membrane	Membrane PVDF					
	Membrane cap	PVDF					
	Protection cap	Protection cap • Vessel: PC Makrolon (polycarbonate) • Seal: Kraiburg TPE TM5MED • Cover: PC Makrolon (polycarbonate)					
	Sealing ring						
Cable specification	max. 3 m (9.84 ft)						

Certificates and approvals

(€mark

Declaration of Conformity

The product meets the requirements of the harmonized European standards. As such, it complies with the legal specifications of the EU directives. The manufacturer confirms successful testing of the product by affixing to it the CC mark.

Ordering information

Product page	:								
root	Exte	nsions							
OCCS50									Base
	AA	Non-	hazar	dous a	area				
		11 99	APPI Proce Spec	LICATI ess Wa ial Vei	ON ater, dı sion, T	rinking SP# t	g water o be specifi	ied	
			<u>AD</u> BF	Mea 0 to 0 to	suring 5 mg/l 20 mg	Range /I	2:		
			_	0A 01 03 99	CABL 0.6 m 1 m 3 m Specia	E LEN 1 al Vers	GTH sion, TSP# 1	to be specifie	d
					NNT WTI	Custo Neut Wed &	omer versio ral test vers gewood An	on sion alytical	
Options:						NB NC N9	Adapter fo Adapter fo Special Ve	or OCCA151 or OCA250 ersion, TSP# t	o be specified

Scope of delivery

The delivery comprises: Disinfection sensor (membrane-covered, Ø25 mm) with protection cap (ready for use) Bottle of electrolyte (50 ml (1.69 fl.oz)) Replacement membrane cap in protection cap Operating Instructions

Accessories

The following are the most important accessories available at the time this documentation was issued.

► For accessories not listed here, please contact your Service or Sales Center.

 2 x membrane caps and 1 x electrolyte 50 ml (1.69fl.oz) 1 x electrolyte50 ml (1.69fl.oz) 2 x sealing set Device-specific accessories Flowfit OCCA151 Flow assembly for chlorine dioxide sensors Flowfit CCA250 Flow assembly for vater and wastewater Modular assembly for vater and wastewater Modular assembly system for sensors in open basins, channels and tanks Material: PVC or stainless steel Photometer PF-3 Compact hand-held photometer for determining free available chlorine Color-coded reagent bottles with clear dosing instructions Order No.: 71257946 Kit adapter (CCS5xD for OCCA151 Clamping ring Thrust collar Order No. 71372027 Adapter kit CCS5xD) for OCA250 Adapter kit CCS5xD) for OCA250 Adapter kit CCS5xD) for OCA112 Adapter kit CCS5xD) for OCA121 Adapter kit CCS5xD) for OCA126 Adapter kit CCS5xD) for OCA127 	Maintenance kit CCV05	Order according to product structure							
Device-specific accessories Flowfit OCCA151 • Flow assembly for chlorine dioxide sensors Howfit CCA250 • Flow assembly for chlorine and pH/ORP sensors HexdipCYA112 • Immersion assembly for water and wastewater • Modular assembly system for sensors in open basins, channels and tanks • Material: PVC or stainless steel Photometer PF-3 • Color-codet reagent bottles with clear dosing instructions • Order No.:71257946 Kit adapter CCS5xD for OCCA151 • Clamping ring • Thrust collar • O-ring • Order No. 71372027 Adapter intcl. O-rings • 2 studs for locking in place • Order No. 71372025 Adapter intcl. O-rings • 2 studs for locking in place • Order No. 71372025 Adapter intcl. O-rings • 2 studs for locking in place • Order No. 71372026 COY8 Zero-point gel for oxygen and chlorine sensors • Oxygen -free gel for the validation, calibration and adjustment of oxygen measuring cells		 2 x membrane caps and 1 x electrolyte 50 ml (1.69fl.oz) 1 x electrolyte50 ml (1.69 fl.oz) 2 x sealing set 							
Kit adapter CCS5xD for OCCA151 • Clamping ring • Thrust collar • O-ring • Order No. 71372027 Adapter kit CCS5x(D) for OCA250 • Adapter incl. O-rings • 2 studs for locking in place • Order No. 71372025 Adapter kit CCS5x(D) for CYA112 • Adapter incl. O-rings • 2 studs for locking in place • Order No. 71372025 Adapter kit CCS5x(D) for CYA112 • Adapter incl. O-rings • 2 studs for locking in place • Order No. 71372026 COY8 Zero-point gel for oxygen and chlorine sensors • Oxygen-free gel for the validation, calibration and adjustment of oxygen measuring cells	Device-specific accessories	 Flowfit OCCA151 Flow assembly for chlorine dioxide sensors Flowfit CCA250 Flow assembly for chlorine and pH/ORP sensors FlexdipCYA112 Immersion assembly for water and wastewater Modular assembly system for sensors in open basins, channels and tanks Material: PVC or stainless steel Photometer PF-3 Compact hand-held photometer for determining free available chlorine Color-coded reagent bottles with clear dosinginstructions Order No.: 71257946 							
Adapter kit CCS5x(D) for OCA250 • Adapter incl. O-rings • 2 studs for locking in place • Order No. 71372025 Adapter kit CCS5x(D) for CYA112 • Adapter incl. O-rings • 2 studs for locking in place • Order No. 71372026 COY8 Zero-point gel for oxygen and chlorine sensors • Oxygen-free gel for the validation, calibration and adjustment of oxygen measuring cells		Kit adapter CCS5xD for OCCA151 Clamping ring Thrust collar O-ring Order No. 71372027 							
Adapter kit CCS5x(D) for CYA112 • Adapter incl. O-rings • 2 studs for locking in place • Order No. 71372026 COY8 Zero-point gel for oxygen and chlorine sensors • Oxygen-free gel for the validation, calibration and adjustment of oxygen measuring cells		Adapter kit CCS5x(D) for OCA250 Adapter incl. O-rings 2 studs for locking in place Order No. 71372025 							
COY8 Zero-point gel for oxygen and chlorine sensors • Oxygen-free gel for the validation, calibration and adjustment of oxygen measuring cells		Adapter kit CCS5x(D) for CYA112 • Adapter incl. O-rings • 2 studs for locking in place • Order No. 71372026							
		 COY8 Zero-point gel for oxygen and chlorine sensors Oxygen-free gel for the validation, calibration and adjustment of oxygen measuring cells : 							

